

Report on Survey of R. N. Floyd #2
and The N.E. $\frac{1}{4}$ of Section 44. E.T. RR Co.
18 mi. S.W. of ^{Montague} Bowie, in Montague Co. Texas.

I ran a traverse around the entire Floyd #2 so as to proportion excess, and later put in corners from the traverse line.

This land is covered with P.O. sandy soil with rock showing along creeks and on hill tops. The country is very rough.

I found the original witness trees at the new corner of J. H. Mansfield 158.7 Ac tract which is Pat. Thence N at the N.E. corner of Richier I chained W to see if E.T. RR Sec 43 had its distance of 1900 rs. result shows on my sketch. Continuing N

I lie in Rock Md near N.W. corner of Floyd and figures my line to pass through it continuing N to an intersection with an old fence line at S.W. cor E & W - E.L. Findley 160 shows no witnesses, and I found nothing that looked like a corner - no fence line going North.

Thence E with old fence line mostly cleared on the left - timber to right - looked for witnesses S.W. corner of Heath but found nothing - at the N.E. corner found Rk Md in E & W fence and a 2nd P.O. marked X facing mound - Have no record of the witness - continuing East at 13475 pass fence going South - at 52075 Rk Md in E & W fence - P.O. marked X facing mound - no record of witness - This md is the S.E. corner of Heath & check for distance - Return to N.E. cor. W. Bremond -

Thence South found no corner but made one 1.513 E of the fence mentioned.

Thence west with old fence line - at 14975. pass Rk Md in said E & W fence - This is N.E. cor of Mansfield - continuing west to beginning.

N.E. 1/4 - of E.T.R.R. Co. - sec.

Begun N 0° 20' W - 422.5' vrs. from N.W. cor. of
Manofield. - Th. W. accepting the Patterson N.E. cor.
for my S.W. corner of Richier. The Patterson has
been patented and is fenced with good fence
4 wires with hog wire at bottom -
Th. North to N.W. cor. Th. E to W. Mt. Floyd.
Th. S. to beginning -

Tried to balance Floyd Survey - no go the angles
were not it. I remeasured every $\times$ and found them
good except a minute in 2 places -
I made the angles close - Then chaining was
in error - I remeasured the entire Floyd & found
140' error on E side & 100' on the North -

The figures then stood 13' diff E & W - 6' N & S.
I am so sure of my chaining now that I
used the distances last found in figuring
the area. Taking the mean of N & S lines $\times$ the
mean of E & W lines -

I say again the country is very rough.
breaking the chain at 10' to 25' for 300' at
a time going into creeks & coming out -

Feb 25 - 1941 -

I have changed the
East Boundary Line of
Floyd #2 to conform with
the construction by Morris
which was accepted by
your Department some
years ago -

J.H. Clement

J.H. Clement
L.S. Land Surveyor
Wichita Falls -

Tx -



Sk. File No. 23

Montague County

T. H. Clement Statement of the
R. W. Floyd Survey in S.W. Part of
county

Filed April 3, 1941
Bascom Giles Com'r

Alvon Rosenberg
File Clerk

Gh²

RECEIVED
APR 3 - 1941
GENERAL LAND OFFICE

count 31755