

E. H. ESTES,

Breeder of

Hereford and Durham Cattle.

372

Midland, Texas, March 3rd

1902

Hon Chas Rogan Commissioner
Austin Tex

Dear Sir:-

The field notes of the Midland County lines has doublets, are these come under your inspection.

To more substantiate the work I would say this, being the surveyor that run the lines.

That I used a new transit of the latest and most approved make. running "hub" lines throughout. and using the needle only to determine the magnetic variation at observation stations. never using it on the line. All measurements were made with a steel tape in the most careful manner.

Code 57195

R

E. H. ESTES,

Breeder of

Hereford and Durham Cattle.

#

Midland, Texas,

190

The lines east and west are run on short tangents and deflections back to parallel and all corners are offset to the parallel. The lines north and south are true meridians.

I located the surveys on which the four County Corners fell and also located the Block lines at intervals which the county lines intersected. I did not locate the corner of each section through which the lines passed for the reason of the great expense to the county it would involve. But thought the locations I made sufficient as the entire country traversed, was ~~and~~ ^{F. and P.} work all right angles and parallel and having no angular or detached surveys.

E. H. ESTES,

37

Breeder of

Hereford and Durham Cattle.

Midland, Texas,

190

You can judge as to the correctness
of the work when I tell you with-
out reserve that I closed the 120
miles around the county 47 feet long
in measurement east and west - and
being "in" north and south 27 feet
after calculations for corrections for
error on the last day's run.

I am yours truly
and hoping that the work will meet
with your approval

Robt G Estes

Co-Surveyor

Midland

Tex

R²

Enter 57197