Pers

REPORT OF A SURVEY of T & N. O. Ry. Surveys 66 and 68 in Duval County, Texas.

This survey is made for Mr. W. P. Murphy of Papalote, Texas, for the purpose of correction and Patents of the above surveys.

Began at a new stake and stone set N. 78° E. 95.0 vs. from the Original Bearing tree Mkd "D", alive and standing, for the Northwest corner of Survey 66. A Mesquite stump Brs. N. 86° E. 48.0 vs., a 12" Mesquite tree, badly cut, Brs. S. 88° E. 35.0 vs. This appears to have been the tree called for N. 86° E. 48.0 vs. by its age and the appearance of the Original cut.

I then ran S. 10212' W., at 1863.1 vs. found a painted Mesquite stake for the Southwest corner of this survey, from which a Mesquite, dead and down, no marks showing, answers the call for course and distance for a Mesquite called for at N. 37° E. 21.5 vs. Clearing has destroyed the tree call for or S. 63° W. 6.5 vs.

Continuing S. 10092 W. at 1954.4 vs. a Mesquite stake for the Southwest corner of Survey 68 from which the Original Brg. tree Mkd. N. 63° E. 35.0 vs., found standing. Intersecting the North Boundary of G. H. & H. Ry. Co. Survey 75, 251.0 vs. East of its Northwest corner a stone, found.

Thence East along the North Boundary of Survey 75, passing a fence corner post for the Northwest corner of Survey 32, at 1944.0 vs. a stone and Mesquite tree Mkd. = found for the Original Southeast corner of Survey 68.

Thence North to a mound of stones with the old stake found below the surface. A Mesquite answers the course and distance but no mark showing. Continue North crossing a small creek and two very old roads, which do not answer the call of the Original notes of 66. The present Northeast corner of Survey 66 is a fence corner post, from which a Mesquite stump answers the call for course and distance. This tree was standing and marked, in 1942 during my survey of the West  $\frac{1}{2}$  of BS&F Survey 526. Showing

Thence West, at 500.0 vs. pass the Southwest corner of Survey 526 and the Southeast corner of Survey 103. The Brg. tree has been destroyed but was found by me in 1942 and noted. The line of 103 and 66 Bears S. 85°14' W. from this point to the Northwest corner of 66.

This Report covers my survey of Surveys 66 and 68 as I did the work, beginning the work from the Northwest corner of 66 South. All corners found on the ground with the exception of the Northwest corner of 66 which was re-located from the Original Bearing tree.

L. M. Brumfield

Licensed State Land Surveyor of Texas

RECEIVED

DEC 8 1953

REFERRED TO MAP

Counter 21456

E SIDE . a.a. TOO 000 for I \* 02 . - 23 b+ 00 . ₩ 03 . SXSX

sample of the order of the standard of the sta

Surveyors Roport Sur-168 68. by L. M. Brumfreld The sand the solution of the sand of the sand the solution and the sand the

tased the coned at 50 to sewid the sear are 0.005 of the southwest of series 103. The search of the Sala motel of the wall moult to the t correction sent of T Survey 103 103 103

Ligad Ligad Terro Report covers my survey selfon and the finors edt no finors a fornot a forn To regree de evergraft of to neitgebre ent dith ss 88 se so respective son respective sections of the sections I did the South. Morthwest and tree.

OL John S